# CDM Smith Daily Status Report

Site Name/Location: Cabo Rojo Groundwater Contamination Site, Cabo Rojo Puerto Rico

**DATE:** 4/12/13 **WEATHER:** 98 Degrees F, Sunny

PERSONNEL ONSITE

#### **CDM Smith**

Frances Delano Patrick Connelly

## **CDM Subcontractor**

Joel Alvarado, driller Luis F. Santiago, driller Orlando Marrero, driller Marcus Garcia, project manager

**FIELD EVENT:** Continue sampling soil vapor

#### FIELD WORK PERFORMED:

Equipment was calibrated and checked

- Field GC Screening results:
  - PE-SV-10 / 3.5 4 ft bgs non detect (ND)
  - PE-SV-02 / 7.5 8 ft bgs PCE 0.049 ppm
  - PE-SV-03 / 8.5 9 ft bgs PCE 0.052 ppm
  - PE-SV-01 / 2.02 2.8 ft bgs ND
  - PE-SV-04/ 8.5 9 ft bgs-ND
  - PE-SV-06 / 4.6 5.2 ft bgs -ND
  - PE-SV-07 / 6.6-7 -ND (while purging line PID had VOCs reading of 2.8)
- Confirmatory Samples collected:
  - PE-SV-10C
  - PE-SV-20C (duplicate of PE-SV-10C)
  - EB-SB-01 (sampling setup check "equipment blank")
- Completed soil vapor sampling at PRIDCO east
- Health and Safety meeting
- Security arrived to site

### Proposed next day event:

• Continue soil vapor sampling at Reto Plant

## **MISCELLANEOUS:**

• José Reyes will be arriving at the site to assist in the sampling.